

Appendix A

Total Particulate Mass Continuous Emission Monitoring System Supporting Documents

The Lilly logo is a stylized, cursive script of the word "Lilly" in a dark gray color. The letters are fluid and interconnected, with a slight shadow effect.

**Version 1.0
November, 2005**

Appendix A

Total Particulate Mass Continuous Emission Monitoring System Supporting Documents

The Lilly logo is a stylized, cursive script of the word "Lilly" in a dark gray color. The letters are fluid and interconnected, with a prominent 'L' and a trailing 'y'.

**Version 1.0
November, 2005**

Table of Contents

1. Performance Specification 11 – Specifications and Test Procedures for Particulate Matter Continuous Emission Monitoring Systems at Stationary Sources, 40 CFR Part 60, Appendix B, January 12, 2004.
2. Procedure 2- Quality Assurance Requirements for Particulate Matter Continuous Emission Monitoring Systems at Stationary Sources, 40 CFR Part 60, Appendix F, January 12, 2004.
3. EPA Draft Guidance Documents on PM CEMS, provided to Eli Lilly and Company by EPA Office of Air Quality Planning and Standards March 3, 2005.
 - a. Precision and Bias Guidance
 - b. Procedure 2 Audits
 - c. Procedure 2 Routine Checks
 - d. PS11 Example Calculations
 - e. PS11 Spreadsheet Example
 - f. Relative Calibration Audit Data Evaluation
 - g. Stratification Procedure

Table of Contents

1. Performance Specification 11 – Specifications and Test Procedures for Particulate Matter Continuous Emission Monitoring Systems at Stationary Sources, 40 CFR Part 60, Appendix B, January 12, 2004.
2. Procedure 2- Quality Assurance Requirements for Particulate Matter Continuous Emission Monitoring Systems at Stationary Sources, 40 CFR Part 60, Appendix F, January 12, 2004.
3. EPA Draft Guidance Documents on PM CEMS, provided to Eli Lilly and Company by EPA Office of Air Quality Planning and Standards March 3, 2005.
 - a. Precision and Bias Guidance
 - b. Procedure 2 Audits
 - c. Procedure 2 Routine Checks
 - d. PS11 Example Calculations
 - e. PS11 Spreadsheet Example
 - f. Relative Calibration Audit Data Evaluation
 - g. Stratification Procedure